

608 Master Repair Kit

Part# K001040

<u>Part Number</u>	<u>Description</u>	<u>Qty</u>
A201032	Master Pinion Support - Assembly	1
A401122	Master Gear Segment - Assembly	1
P001740	Motor - Gear	1
M001050	Insulation switch	1
P001030	Bearing – Radial Ball Bearing	2
P001150	E- Ring Bowed	1
P001220	Screw – Pan Head Phillips 8-32 x .375	4
P001250	Screw – Pan Head Phillips 4-40 x .250	2
P001260	Screw – Pan Head Phillips 4-40 x .875	2
P001280	Screw – Pan Head Phillips 10-32 x .313	4
P001290	Screw – Pan Head Phillips 10-32 x .500	5
P001320	Screw – Pan Head 10-32 x .250	4
P001330	Screw – Pan Head Phillips .250-20 x 1.0	4
P001340	Screw – Pan Head Phillips .250-20 x 1.250	4
P001450	Lockwasher – Internal Tooth .250	14
P001460	Lockwasher – Internal Tooth No. 4	4
P001470	Lockwasher – Internal Tooth No. 8	11
P001480	Lockwasher – Internal Tooth No. 10	15
P001920	Washer – Nylon No. 8	2
P001980	Screw – Pan Head Phillips 8-32 x .313	4
S001070	Shim .005	1-4
P001570	Micro Switch	2
A501091	Motor Wire Harness	1
P001520	Spring Link Switch Actuating	1
A201010	Case Divider Assembly	1
M001570	Spring, Needle Return	1
M001460	Spring, Tension	1

Freight: FOB Tustin, CA

Terms: Net 30 days

Prices subject to change without notification

PT608_MRK 020108

